

## What is it?

NFWP is a New & Improved VIP Program offered to eligible installers that provides the following: "NAPA Ironclad commits to eligible Installers that any NAPA Ironclad gasoline engine purchased will be covered against failure due to installation error or non NAPA Ironclad component failure, providing that the original NAPA Ironclad warranty is still in effect."



## When does NFWP coverage begin and end?

NFWP coverage on a product runs concurrent with the original NAPA Ironclad warranty.

## What does it cover?


NFWP will cover all first time product failures on NAPA Ironclad products not covered under the original NAPA Ironclad warranty that are a result of an installer error or other non NAPA Ironclad component failure. Examples of covered failures include:

- Detonation
- Dry Start
- Thrust Bearing Failure
- Contamination
- Ingesting Debris or Foreign Objects
- Overheating

## What is not covered?

Causes of failure that are not covered include:

- Lack of Maintenance/Electrolysis
- Racing or Any Competition Use
- Off-highway Use
- Accident and/or Acts of God (floods, etc)
- Incorrect Application or Misuse
- Unauthorized Repairs of Any Kind
- Freight Damage



## How to become eligible to become a NFWP installer?

You must be a licensed professional repair facility within the United States, who purchases NAPA Ironclad products directly from NAPA AUTO PARTS Store and installs them in customer vehicles. Additionally Installers must remain in Good Standing in the NFWP program<sup>1</sup>. An engine purchase must be installed at a licensed repair facility. A retail engine purchase must also be installed at a licensed repair facility.

## Where can NFWP service be performed?

At the original installation facility, however if the vehicle cannot be brought back to the original facility NFWP service can be performed at any NAPA Auto Care Center, or at a service center that is licensed to do OEM warranty work on the vehicle being repaired.

## Labor Rate?

Standard labor rate for NFWP is up to \$50 an hour Mitchell labor time guide.



<sup>1</sup> In order to remain in Good Standing an installer must keep their customer account current and must not, in NAPA Ironclad's sole discretion, abuse the NFWP program by have submitted an inordinate amount of claims under the program. Installers not in Good Standing will be informed by mail and at the time of the next purchase.

# Remanufactured NAPA Ironclad Engines

## No Fault Warranty Program (NFWP)

Covers replacement of engine as the automotive plan does and labor at \$50 per hour.

**3 YEARS NO FAULT  
UNLIMITED MILEAGE  
WARRANTY**



**NFWP**

	INCLUDED
Warranty – Gas Engines*	3 Years Unlimited Mileage
Labor Policy (first replacement)	Up to <b>\$50</b> per hour (first time failure) Factory time guide
Foreign Object(s) and/or Debris	✓
Overheating	✓
Overrevving	✓
Detonation or Pre-ignition	✓
Cracked Block or Head(s)	✓
Burned or Melted Pistons	✓
Lack of Lubricant or Fluids	✓
Rust, Corrosion or Damage Caused by Electrolysis	✓
Dry Starts or Thrust Bearing Failure	✓

Failure Resulting From:

\* Non-commercial and under 11,000 GVW automotive applications



For more information call  
**800.831.5947**

Effective 4/2012 | ©2012 NAPA Ironclad. Visit us online at [www.napaironcladengines.com](http://www.napaironcladengines.com)